Approved For Release 2000/09/01: CIA-RDP81B00878R001400110167-6

C

15 May 1956

CMCC Doc. No. 151X5.111 Copy 1 of 2 Page 1 of 1

25X1D

Dear Harry:

25X1A

25X1A

25X1D

has asked me to forward to you a correction to the sensitivity data for System 1, CMCC No. 166X5.1, which Burt sent you on 26 April. Jim pointed out that the minimum detectable signal into the crystal, reported as , was not consistent with the minimum detectable signal into the antenna. Dr. has rechecked all of the data and, in examining the original data, discovered that the signal level into the crystal was in fact recorded as - which should convert to power. The conversion was apparently incorrectly made initially. No other discrepancies were found in the data. Will you please change your copy of the data accordingly?

25X1D

Sincerely.

Bob

25X1A Original sent to Copy sent to 25X1A

25X1A